HITACHI SERVICE MANUAL PA No. 0043

21MS4B

NTSC

FH92XS-1 (FU30H/M031) CHASSIS

R/C: CLU-241C

This service manual only gives differences between the 21MS4B and 21MS2B. For any other information see the 21MS2B Service Manual PA. No. 0032 issued in August 1993 and the 20MA1B Service Manual FH No. 0601E issued in May 1993.

## REPLACEMENT PARTS LIST

This parts list only gives parts which are different from the 21MS2B.

**PRODUCT SAFETY NOTE:** Components marked with a  $\triangle$  have special characteristics important to safety. Before replacing any of these components, read carefully, the PRODUCT SAFETY NOTICE in the 20MA1B Service Manual. Do not degrade the safety of the receiver through improper servicing.

SYMBOL NO.	PART NO.	DESCRIPTION	SYMBOL NO.	PART NO.	DESCRIPTION
△ SP451	2412515	SPEAKER 90 X 50 (16Ω)	#	2956675	2J LEAD WIRE WITH FASTEN TAB
⚠ SP452	2412515	SPEAKER 90 X 50 (16Ω)	N201	H461342	INSTRUCTION BOOK

NOTE: This is a Mexico only model and it is not sold in the United States of America or Canada. This is a Monaural Model with two speakers that are connected in parallel.

SPECIFICATIONS AND PARTS ARE SUBJECT TO CHANGE FOR IMPROVEMENT

**SOLID STATE COLOR TELEVISION** 

DECEMBER 1994

**HHEA - MANUFACTURING DIVISION** 

- B

HITACHI

\*I

PA0043