





	G	F	E	D	C	B	A	POINT	H.F.	BR	GALV		SM ROTATION	SM SPRAY
*											+1		SM BROSSE	+2
							+3	SPRAY			+4	SM H.F.	SM CAL	+5
#							+6				+7	SM MODE GAL		SM INC. +8
									POS		NEG	+10	SM DEC.	+11