

PA

No.0012

27DX5B

NTSC

A1LXU-M/R

R/C:CLU-671GJ

This service manual only gives differences between the 27DX5B and CT7897B. For any other information, see the CT7897B Service Manual YK No. 0420E issued in December 1991.

## **REPLACEMENT PARTS LIST**

This parts list only gives parts which are different from the CT7897B.

PRODUCT SAFETY NOTE: Components marked with a \( \frac{1}{2} \) have special characteristics important to safety. Before replacing any of these components, read carefully, the PRODUCT SAFETY NOTICE of this Service Manual. Don't degrade the safety of the receiver through improper servicing.

SYMBOL NO.	PART NO.	DESCRIPTION	SYMBOL NO.	PART NO.	DESCRIPTION
	3142473	WOOFER BOX ASS'Y (HHEA MD)	/ E201	2982473	300-75 VHF ADAPTOR
	3104614	FRAME ASS'Y (HHEA MD)	↑ E301	2573784	REMOTE CONTROL TRANSMITTER
<u> </u>	3163606	BACK COVER ASS'Y (HHEA MD)	<u> </u>		CLU-671GJ (NOTE 1.)

NOTE 1. The 27DX5B was produced with two different Remote Controls: CLU-671GR or CLU-671GJ. These Remote Controls are functionally equivalent.

Order CLU-671GJ (Part No. 2573784) as replacement Remote Control.



SPECIFICATIONS AND PARTS ARE SUBJECT TO CHANGE FOR IMPROVEMENT.

SOLID STATE COLOR TELEVISION

July 1992

**HHEA - MANUFACTURING DIVISION** 

## HITACHI

## HITACHI HOME ELECTRONICS (AMERICA), INC.

National Headquarters
3890 Steve Reynolds Blvd., Norcross, GA 30093 Tel. 404-279-5600
Western Regional Office
401 West Artesia Blvd., Compton, CA 90220 Tel 310-537-8383
Eastern Regional Office
1290 Wall St. West, Lyndhurst, NJ 07071 Tel. 201-935-8980
Mid-Western Regional Office
1400 Morse Ave., Elk Grove Village, IL 60007 Tel. 708-593-1550
Southern Regional Office
3890 Steve Reynolds Blvd., Norcross, GA 30093 Tel. 404-279-5600

HITACHI SALES CORPORATION OF HAWAII 3219 Koapaka St., Honolulu, Hawaii 96819 Tel. 808-836-3621

HITACHI SALES CORPORATION DE PANAMA, S.A. Centro Comercial Plaza Balboa, Punta Paitilla P.O. Box 7657, Panama 5, Republic of Panama Tel. 63-6491 63-6500