


Service
Service
Service



02B/03B/09B/11B/13B
63NA1076/18B
63NA1077/06B
63NA1276/18B
70NA1147/
02B/03B/09B/11B/13B
70NA1176/18B
70NA1177/06B
70NA1376/18B



Service manual 4822 727 18428 is herewith cancelled

Service Manual

Safety regulations require that the set be restored to its original condition and that parts which are identical with those specified be used.

Les normes de sécurité exigent que l'appareil soit remis à l'état d'origine et que soient utilisées les pièces de rechange identiques à celles spécifiées.

Chassis GR2.1

MDA.02983
T19/112


RC6502



220-240 V ($\pm 10\%$)
140W max.



UV916: 45-855 MHz



a x b x c (mm)
25": 730x535x447
28": 788x581x485



2 x 20W
8Ω



- /06B/18B: PAL BGI
SECAM BGLL'

- /02B: PAL BG
SECAM BG

- /03B/09B: PAL BG

- /11B/13B: PAL BG NICAM

OPTIONS

OPTIONS	PIPE	TELETEXT	AUTO STORE	MULTI SYSTEM	HYPERBAND	UHF ONLY	INCAM TWIN
-/06B	X	X	X	X	X		
-/18B	X	X	X	X	X		
-/02B/03B/09B	X	X	X	X	X		
-/11B/13B	X	X	X	X	X		X



- CS 57 287