



# 11AK19 MAIN CHASSIS

SAFETY COMPONENTS MARKED WITH A **⚡** MUST BE REPLACED  
 ONLY BY QUALIFIED PERSONNEL AND MUST BE REPLACED WITH IDENTICAL SAFETY COMPONENTS.  
 ATTENTION: THE SAFETY COMPONENTS ARE NOT TO BE REPLACED WITH OTHER SAFETY COMPONENTS.  
 THE REPAIR WORKSHOPS MUST BE ADVISED TO CHANGE THE BEARING AND  
 THE REPAIR WORKSHOPS MUST BE ADVISED TO CHANGE THE BEARING AND

YUV INTERFACE SOCKET

HORIZONTAL OUTPUT

TEXT & CONTROLLER

VERTICAL OUTPUT

VIDEO PROCESSOR

STEREO DECODER BOARDS SOCKETS

AUDIO SWITCH

VIDEO SWITCH

AUDIO OUTPUT

S-VHS SERVICE PLUGBONT AV

PL 900