




IMPORTANT SAFETY NOTICE
THE SYMBOL MARK OF THIS SCHEMATIC
DIAGRAM INCORPORATES SPECIAL FEATURES
IMPORTANT FOR PROTECTION FROM X-RADIATION.
FIRE AND ELECTRICAL SHOCK HAZARDS WHEN
SERVICING IT IS ESSENTIAL THAT ONLY
MANUFACTURER SPECIFIED PARTS BE USED FOR
THE CRITICAL COMPONENTS IN THE SYMBOL
MARK OF THE SCHEMATIC.

WAVE FORM
CONDITION
1. MODE
MODE 5
53.68kHz/85.07Hz
2. INPUT VOLTAGE
AC 115V
3. PATTERN
FULL WHITE